



Storage bags should be used under 2 degrees gradient. Depending on the requirement they may be manufactured in different capacities. Filling apparatus is 2".

STORAGE BAG 3-5-10-25-50-100